MODEL: T500 REVISION: D DATE: Dec. 13th, 2022



FITTING INSTRUCTIONS:

Before fitting the respirator, *carefully inspect the entire respirator* to ensure that the respirator is not damaged and is functioning correctly. *Discard the entire respirator if any part does not function properly*.

- 1. Hold the respirator in your hand with the nosepiece at your fingertips and allowing the straps to fall below the hand.
- 2. Place respirator under the chin with the nosepiece (narrow end) up. Pull the continuous bottom strap over your head and position it around the neck below the ears.
- 3. Raise the continuous top strap over your head and place it high to the back of the head.
- 4. Using both hands, push the nosepiece inwards with your fingertips to mold and shape the nose area to the face.
- 5. Without removing the respirator, adjust the straps until the respirator is secure. To tighten the respirator, gently push the adjusters of both straps. To loosen the respirator, pull the adjusters to the end buckles of both straps.
- 6. A seal check MUST be performed each time the user enters a contaminated area. Lightly cup both hands over the front of the respirator and exhale powerfully. If any air flow is detected around the edges of the respirator, readjust the straps. Repeat seal check until a proper seal is achieved; otherwise, see your supervisor. *NEVER enter a contaminated area without a proper seal*.

Note: Pinching the nosepiece using one hand may result in improper fit and less effective respirator performance. Use two hands.

Manufacturer Address:

Fido Mask Co., Ltd

No. 31, Gong 1st Rd., Dajia Dist., Taichung City 437, Taiwan (R.O.C.)

TC-	Protection ¹	Respirator	Cautions and Limitations ²
		T500	
84A-8117	R95	X	ABCJMNOPS